Division of Health Care Facilities

STATE FORM

PRINTED: 10/17/2017 FORM APPROVED

(X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY IDENTIFICATION NUMBER: AND PLAN OF CORRECTION COMPLETED. A. BUILDING: 01 - MAIN BUILDING 01 8 WING TN4710 10/16/2017 NAME OF PROVIDER OR SUPPLIER STREAT ADDRESS, CITY, STATE, ZIP CODE **909 EAST EMERALD AVE** NHC HEALTHCARE, KNOXVILLE KNOXVILLE, TN 37917 SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST SE PRECEDED BY FULL PROVIDER'S PLAN OF CORRECTION CK\$1 (X4) ID PREFIX DATE PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LISC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY 1200-8-6-.08 (17) Building Standards N 847 No residents were affected by this 11/3/17 practice. (17) The licensed contractor shall not install a system of water supply, plumbing, sewage, All residents have the potential to be garbage or refuse disposal nor materially alter or extend any existing system until the architect or affected by this practice engineer submits complete plans and specifications for the installation, alteration or The maintenance department extension to the department demonstrating that adjusted the water tempering system all applicable codes have been met and the department has granted necessary approval. for the facility to the appropriate level of between 105 to 115 degrees for the (a) Before the nursing home is used, Tennessee past week and reported to the QAPI Department of Environment and Conservation meeting 10/26/17. The center shall approve the water supply system. consulted with a licensed plumber to (b) Sawage shall be discharged into a municipal find a solution to the inconsistent system or approved package system where temperatures at the shower, bathing available; otherwise, the sewage shall be treated and hand washing to remain within and disposed of in a manner of operation approved by the Department of Environment and 105 to 115 degrees. Conservation and shall comply with existing codes, ordinances and regulations which are The facility will report the water enforced by cities, countles or other areas of local political jurisdiction. temperature for the locations in question for hte next 3 months to the (c) Water distribution systems shall be arranged QAPI committee, The QAPI to provide hot water at each hot water outlet at all Committee consists of the Medical times. Hot water at shower, bathing and hand washing facilities shall be between 105°F and Director, Director of Nursing, 115°F. Administrator, Dietitian, Director of Rehabiliation, Director of Social Services, Business office manager, Director of Activities and other This Rule is not met as evidenced by: Based on observation and testing, the facility department heads. failed to provide hot water temperatures within 105°F to 115°F in 5 of 7 observed rooms. The findings include: Division of Health Care Facilities LABORATORY DIRECTOR'S BE PROVIDER/BUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE

T. Bradley Shuford

G109

DDHK21

Administrator

if continuation sheet 1 of 2

PRINTED: 10/17/2017 FORM APPROVED

Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 - MAIN BUILDING 01 B. WING \_ TN4710 10/16/2017 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, 7IP CODE **809 EAST EMERALD AVE** NHC HEALTHCARE, KNOXVILLE KNOXVILLE, TN 37917 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX LEACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) N 847 N 847 Continued From page 1 Observation and testing on 11/16/17 between 9:30 AM and 11:30 AM revealed the following locations did not have water temperatures within 105 °F to 115 °F: 1. 1st floor main bathroom water temperature of 123.8°F. 2. 257 sink water temperature 123.3 °F. 3. 219 sink water temperature 115.5 °F. 4. 276 sink water temperature 116.2 °F. 5. 2 East whirlpool room water temperature 118.0°F. The maintenance director was present when the deficiencies were identified and acknowledged by the Administrator during the exit conference on 10/16/2017